

MONUMENT RECORD

State of Indiana - County of Monroe

Section: 23

Township: 9 North

Range: 1 West

Corner ID: Blm S-17


Monument Description & Remarks: Found crimped Iron Pipe, 8" out of ground, at South $\frac{1}{4}$ corner of section. Metal fence post on north side of pipe; broken, moss covered limestone laying on the east side of pipe. Old barbed wire cross fencing to the north/south and east/west.

References On File: Lake Griffy Boundary Survey, dated May 4, 1998, on file in the County Surveyor's Office.


RECOVERY TIE DRAWING

Field Book 99-01 Page No. 47

USGS Unionville Quad



- A - crimped iron pipe
- B - South 05° West, 23.62' from pipe
Old witness nail in 23" Yellow Poplar
- C - North 77° West, 11.26' from pipe
MAG nail in 6" White Oak
Survey marker sign set 5' up
- D - North 09° West, 8.87' from pipe
MAG nail in 14" Red Oak



• At Corner

Not To Scale

Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 9th day of August, 1999.

Kevin P. Enright

Administered by the Monroe County Surveyor Review Board

Date: 10/21/99

